Date:

Tuesday, 11/29/2005 10:25:23 AM

Linda Lacelle User:

Process Sheet

Customer Job Number : CC-DAR01 Dart Aerospace Ltd.

S.O. No. :

Type

: 24978

Estimate Number

: 10804

P.O. Number

: 11/29/2005

This Issue

: NC Prsht Rev.

: 11/29/2005 First Issue : 00015

Previous Run

Written By

Checked & Approved By

Comment

Additional Product

Job Number:

Seq. #:

Machine Or Operation:

SMALL FAB 1

Comment: SMALL & MEDIUM FAB RESOURCE 1

DISASSEMBLE 1 X D3137-041 B23576: - reme(12

4 DJ 195

1.0

1 X D3137-1 B18659

1845 187

1 X D3137-3 B 17477 1 X D3137-5 M10536

1 X MS24694S101 / 6 9 9

ADJUST INVENTORY

PACKAGING 1 2.0

DC

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1 MS 2-4694 S 101

ID & STOCK

D3137-5



Comment: DOCUMENT CONTROL

Job Completion

3.0



Drawing Name

: DISASSEMBLE

Part Number

Drawing Number Project Number

Drawing Revision

Material **Due Date**

Description:

SMALL & MEDIUM FAB RESOURCE 1

: 12/6/2005

: Z_CUSTOM

: Z_CUSTOM

Qtv:

Um:

05/11/29

Each

Page 1

Dart Ae	rospace	Ltd								
W/O:			WOI	RK ORDER CHAN	GES					
DATE	STEP	PRO	OCEDURE CHAN	GE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			** ,0,							
Part No		PAR #:	Fault Catego	ory:	NCR	: Yes N	lo DQ/	A :	Date:	
						QA: N/	C Closed	d:	Date:	
NCR:		· ·	WORK ORDE	R NON-CONFORM	MANCE	(NCR)				
		Description of NC	С	orrective Action Se	ection B		Verific	ation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	1	Sign & Date	Section		Chief Eng	QC Inspector

NCK.			•		,			
DATE STED Description of NC				Corrective Action Section B			Annroval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector
			,					
				•				

NOTE: Date & initial all entries

DART AEROSPACE LTD

Work Order:
Part Number:
Description: Bracket assembly

Drawing: D3137 Rev.A1

Qty:

Step	Location	Procedure	Ву	Date	Qty			
1	EXPEDITING 2C	Issue Work Order traveller	K	03.01.15				
27	STORES 64	Pick: Oty Part number Description Batch 1 D3137-1 Bracket Bracket Bracket 1 D3137-3 Guide Guide		030319				
38	METAL GA	Assemble as per dwg. D3137-2417	W	030324	らら			
49	QC 5	Inspect Level 7 work to step 8	193	03.04.01	15			
810	STORES ST	Identify and stock as D3:37-041	160	03-04-021	19			
8,,	EXPEDITING	Close W/O Inspect level 21 Cost/part C/, 0/ Suc 03/04/02 (15)	1/	03,04.02	_			
	24,01							

Rev	Date	Change	Revised By	Approved
A	02.05.16	New Issue	NG	(1) (15 20)
AI	03.61.14	Modity procedures	* Ox=	2.03.30
		The state of the s	i KT	G 03. 01.14

RELEASED

2	ST	Pick	ne	03/03/10	15
3	MV	Machine slot pe, Dwg. D3137 Detail B. Identify as D3137-1. Engrave Dart PlN. Remove Premier ID.	nd	03/83/10	15
4	QCZ	Inspect parts as they come off the cuc machine	0		
5	MU	Debur	2018	1	15
۵	QC 8	Secend check	FZ	, 0 - , , 0	15
	3	3 MV 4 QCZ 5 MV	Gty Part Number. Description Betch 1 830-23001-105/-106 Brecket M10536-17 3 MV Machine slot per Dwg- B3137 Detail B. 1 dentify as D3137-1. Engrave Dat PlN. Remove Premier ID. 4 QCZ Inspect parts as they come off the anachine 5 MV Deburr	Gty Part Number. Description Betch 1 830-23000-105/-106 Breaket M10536-17 Mid 3 MV Machine slot per Dung- D3137 Detail B. 1 dentift as D3137-1. Engrave Dat PlN. Remove Premier ID. Mid 4 QCZ Inspect parts as they come off the CNC machine 5 MV Deburr 6 QC8 Second check	Gty Part Number. Description 1 830-23007-105/-106 Breaket M10536-17 My 03/03/10 3 MV Machine slot pe, Dwg. B3137 Detail B. 1 dentify as D3137-1. Engrave Dat PlN. Remove Premier ID. 4 QCZ Inspect parts as they come off the CNC machine 5 MV Deburr 914 03/03/10

* TALK TO DAND SHEPHERD BEFORE POINC. # 03.01.14

ERIC CHAMBONNEAU CAME TO SEE ME BEFORE STANGAL #03.04.02

REFERENCE ONLY

DART AEROSPACE LTD	Work Order:	23576
Description: Custom W/O to rework bracket	Part Number:	D3137-041
Dwg: D3137 Rev. D PAGE 1 \$ 2		
Ref: N/A		Page 1 of 1

Step	Location	Procedure	Ву	Date	Qty
1	DC	Issue Traveler	X	05,06,14	
2	ST	Remove from store.			
	RF05:08:5	QtyPart NumberDescriptionBatchD3331-041Bracket Ass'yB 18659	Œ	05.08.07	10
3,4	, MV	Disassemble and cut to 0.250" in length at Ø0.560 as per dwg. Save MS24694-S101 srews in store with batch: M11735	B	05.07.07	10
4	QC5	Inspect work to Step 3.	2	5-09-21	13
5	MV	Assemble as per dwg. Oty Part Number Description MS24694-S98 Screw Sico Batch HM16255 M 18 43 1	m	0509-26	9
6	ST	Identify and Stock D3137-041.	mil	05-09-26	9
7	AC	Charge to project number P602-2250 Cost / part: 29,09		05.69.79	9
8	DC	Close W/O Z 8, /3 Inspect Level 21	B	05/61/28	9
	(Note	: Attach a copy of Custom W/O to each of the W/O's listed in S	tep 2 a	bove)	• •

Rev	Date	Change	Revised By	Approved
A	05,06,14	New Issue	KJ/RF	

- 3B GA Deburr

E 05.09.21 10

PTO

PTO

;- 7 C

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES		
DATE	STEP	PROCEDURE CHANGE	Ву	Date
	<u> </u>			

NCR:		WC	ORK ORI	DER NON-CONFORMANCE	= (NCK)	
TOTAL TOTAL				Corrective Action Section B		Veri
DATE	STEP	Description of NC Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date	Sc
05-04.21	3A	/x D3137-1 is machined .030 unclear fuller rance.	MINT	Scrapi des trens	05-15-21	05
05/01/22	5	Some parts misseng to finish the assig	18 05,512	Pick in store 3 x 03137-3 Guide32372 5 x D 3137-5 Washer m10536-17	9 ml 36	c.
		**				

	5.55 ()	Fault Category:	NCR:	Yes (No)	DQA:
Part No:	PAR #:	raun Gategory.			
				0 . NIO C	Incad:

NOTE: Date & initial all entries

QA: N/C Closed:





	DESIGN	V DR	AWN BY	
Ì	-	#	本	DART AEROSPACE LTD
1	CHECK	EDAL API	PROVED	HAWKESBURY, ONTARIO, CANADA DRAWING NO.
		#	W.	REV. D
		7		D3137 SHEET 1 OF 4
	DATE			TITLE SCALE
	04.1	1.03		BRACKET ASSEMBLY
	^			1.1
i	A		2.04.17	NEW ISSUE
	В	С	3.01.16	ADD RIDGES; ADD MAT'L PROP.
				MATE PROP.
	С	0	3.08.15	ADD -043
	D	0	4.11.03	PE_DECICAL D7477 5 CHANGE
-			1.11.00	RE-DESIGN D3137-5; CHANGE DIMS

05.09.26 A. 35.06.14

£98 5100

MS24694-S101 SCREW

.D3137-5 WASHER

D3137-3 GUIDE

INSTALL ON SAME SIDE AS C'SINKS

(OPPOSITE SIDE FROM RIDGES)

SHÓP COPY

RETURN TO **ENGLINEERING**

UNCONTROLLED COPY

SUBJECT TO AMENDMENT

WITHOUT NOTICE

WORK ORDER

NO. 23576

D3137-1 BRACKET (-041 SHOWN)

OR

D3137-7 BRACKET (-043 SIMILAR)

